

TECHNICAL DATA SHEET

R8ED+ 12

Workwear

Article NO: H9743 (blue)
 H9744 (black)
 H9745 (brown)



Material: 96 % polyester, 4 % spandex
Material - lining: 100 % polyester
Grammage: 300 gsm
Size: S - XXXL

Designer men's softshell vest with reflective imprint.

Description: waterproof 5 000 mm, breathability 5 000 mm, TPU membrane, lining 100% polyester, the back part of silver mesh, closing on reverse zipper covered flap, three pockets, interior pocket, precise finish lining, bottom rim using a stopper.

This personal protective equipment is in conformity with these harmonized European Standards:

ČSN EN ISO 13688:2013: Protective clothes - General requirements.

PPE of the simply construction against minimal risk, which can be recognized by the user early and safely.

Self certification has been performed on the base of technical documentation of the PPE and practical exams of the ergonomic features of the PPE by the ARDON SAFETY s.r.o. company, dated 12th December 2018.

Collection R8ED meets the requirements for medical harmlessness and is certified according to STANDARD 100 by OEKO-TEX®, certificate no. PG020 199787



| | |
|---------------------------|----------------------|
| Pieces in carton: | 20 pcs |
| Carton weight: | 25,0 kg |
| Carton size: | 0,138 m ³ |
| Polybag packing (pieces): | 1 piece |

Service life depends on the frequency of use and the wear rate under the given conditions. Improper storage and improper maintenance and handling will reduce the service life. The warranty period is 24 months. In no event may the warranty period be confused with a product's service life. Under intense use, the service life may be shorter than the warranty period. The product contains no substances at concentrations that are known or suspected to have adverse effects on sanitation or a user's health. However, skin irritation may occur with sensitive persons; in this case, the discontinue use of the clothing. Avoid fire and intense heat sources. There are no designated accessories or spare parts for this clothing. When a garment is not being worn, it should be stored in dry and well ventilated places out of direct sunlight. In order to transport, the original packaging should be used. Protect from moisture and extreme temperatures. After use, dispose of in an environmentally friendly manner.