



ARDON®
WORKWEAR
& OUTDOOR

ARDON® BRUNO+

INDUSTRIAL BUMP CAP



TECHNICAL DATA SHEET



ARDON®
WORKWEAR
& **OUTDOOR**

ARDON® BRUNO+

INDUSTRIAL BUMP CAP

ARTIKL No.
D1310 – black
D1311 – blue
D1312 – green
D1313 – Hi-Viz yellow
D1314 – Hi-Viz orange

MATERIAL
ABS, Cotton

COLOURS
Black, Blue, Green, Hi-Viz yellow, Hi-Viz orange

SIZE
UNI

DESCRIPTION

Stylish, modern, impact-resistant sports cap with ventilation holes for comfortable wearing. ABS shell with foam insert. Reflective strips for increased visibility. Easy size adjustment using a dry zip in the range of 54-59 cm circumference. Intended use: agriculture, recreation, gardening, sports activities.

*This cap protects the user from contact with stationary objects such as low ceilings or hanging objects. It is not intended to protect against falling objects.

STANDARDS

This personal protective equipment is in conformity with these harmonized European Standards:

EN 812:2012 : Industrial bump caps.

Certified by notified body No. 2754 ALIENOR CERTIFICATION (ZA du Sanital – 21 Rue Albert Einstein - 86100 CHATELLERAULT - France), Certificate No.: **N° 2754/2737/158/01/24/1175**, issued on 26th of January 2024.

The hi-vis orange and hi-vis yellow bump caps also comply with §5.1.1; §5.2; §6.1 and §6.2 of EN ISO 20471+A1:2016.

UNITS IN A CARTON	60 pcs
CARTON WEIGHT	11,5 kg
CARTON SIZE	0,136 m ³
UNIT PACKAGING	1 pc

This working cap does not provide unlimited protection. For your own protection read the instruction carefully. When not in use, it is recommended to store this working cap in a clean and dry environment and placed away from direct sunlight and out of sources of solvents. This working cap is designed for your personal safety. It must be worn during the whole duration of exposure to any potential hazard. Leave the work area immediately if the working cap becomes damaged. To maintain your working cap in optimum conditions do not use any abrasive materials or solvents and clean any part of the working cap with warm soapy water and dry with a soft cloth. A mild disinfectant can also be used, in line with the manufactures instructions, if required. Only use original accessories and spare parts (harness made and supplied by the manufacturer). Inspect for damage regularly. If the shell or harness, working cap show any signs of damage, it must be replaced immediately. The shelf life of this product, if stored and used correctly, is indefinite. However, we would recommend it be changed every 2-3 years as necessary precaution.